



HOW TO ENTER SIMULATION MODE

Ensure you have the Rexroth program key inserted.

- STEP 1** Turn the Rexroth CS-440 on.
- STEP 2** Make sure the CS-440 is not in pause mode. If the screen displays pause, press IN the spinner dial to turn the pause off.
- STEP 3** Turn the program key ON.
- STEP 4** The menu settings will now appear on the screen.
 - Arrow down to select **system setup**
 - Press enter
 - Arrow down until **'SIM Speed'** appears
 - Press enter
 - The screen will now return to the previous menu. At this point turn the program key OFF
 - The screen will now display spreader and spinner data
 - Press escape
 - The screen will now display trip summary
 - Arrow up (status displays)
 - Arrow up. Ground speed will change at 5km/hr increments; continue until ground speed is set to 20km/hr
 - Press Esc
 - Call Certified Tracking Solutions to test
 - Now you can change spinner and conveyor dials to any value
 - Pause unit by pressing IN the spinner dial
 - Remove from simulation mode once testing complete

IMPORTANT

MUST BE TESTED

CALL TO TEST GPS TRACKING DEVICE BEFORE CLOSING UP DASH

FAILURE TO FOLLOW THESE INSTRUCTIONS MAY DAMAGE EQUIPMENT AND VOID ITS WARRANTY

CALL NOW

1.780.391.3800

TOLL-FREE 1.855.287.4477 (CTS4GPS)

CERTIFIED TRACKING SOLUTIONS